
Access Road Behind Corona Circle

- **Existing easements:**
 - 10-foot sewer easement (1969)
 - 15-foot sewer access easement (1994)
- Homes were developed with Rockmoor Estates Unit 2 Subdivision in 1994.




Access Road Behind Corona Circle

- Access critical to meet State Water Resources Control Board permit obligations (Order 2006-0003-DWQ).
- Access road required to support District's maintenance vehicles (including Hydro-Vac, TV truck and other District equipment).
- High-risk facility due to proximity to wetlands.
- * Access restricted previously due to topography, trees and encroachments.
- Improvement plans currently specify:
 - 3-inches of asphalt on 8-inches of aggregate base behind Granite Bluff lots (knuckle at west end of Corona Circle).
 - 6-inches of aggregate base behind the existing homes.



Looking west from El Don Drive towards the access road at the gate location.



GrassPave2 Characteristics:

- Structural integrity to support District's maintenance vehicles.
- ❖ Blends into the surroundings since native grasses are able to grow within the cells.
- Serves as a physical barrier within the District's easement.
- Mowing will be required periodically.
- ❖ 60-year life
- **❖** Change Order #5 − \$68,300



Looking east behind Corona Circle. No previous access to Manhole I10-045.

