## SPMUD Condition Assessment

JULY 7, 2022

## **Condition Assessment - Systems**

CCTV InspectionSoftware

►ITpipes

Standardized CodingNASSCO PACP





## Condition Assessment - Uses


Inspection-Driven Cleaning

➤ Effective cleaning

≻Save water

➢ Frees up crew for other work tasks

Stretch	Grade=0	Up MH	Up MH Street	Dn MH	Last Clean	Years Since	Hot Spot?	Diameter D	istance Cont.	Date	Code	Description	Value 1	Value 2	%	Grade
88	4	(PSR)			60	Last Clean	0	(in)	(ft)							
1	0	106-124	SOUTH WHITNEY BLVD	106-046	12/23/2013	8.4	#N/A	6	0	5/24/2022 10:19	AMH	Access Point Manhole				
0	0	106-124	SOUTH WHITNEY BLVD	106-046				6	0	5/24/2022 10:19	MWL	MISCELLANEOUS WATER LEVEL			0	
0	0	106-124	SOUTH WHITNEY BLVD	106-046				6	1.6	5/24/2022 10:19	RFJ	Roots Fine Joint				1
0	0	106-124	SOUTH WHITNEY BLVD	106-046				6	2.9 S01	5/24/2022 10:19	RFB	ROOTS FINE BARREL				2
0	0	106-124	SOUTH WHITNEY BLVD	106-046				6	9 F01	5/24/2022 10:19	RFB	ROOTS FINE BARREL				2
0	0	106-124	SOUTH WHITNEY BLVD	106-046				6	12.3	5/24/2022 10:19	TFA	TAP FACTORY ACTIVITY	6			
0	0	106-124	SOUTH WHITNEY BLVD	106-046				6	25.6	5/24/2022 10:19	TFA	TAP FACTORY ACTIVITY	6			
0	0	106-124	SOUTH WHITNEY BLVD	106-046				6	78.9	5/24/2022 10:19	TFA	TAP FACTORY ACTIVITY	6			
0	0	106-124	SOUTH WHITNEY BLVD	106-046				6	80.9 S02	5/24/2022 10:19	DAGS	Deposits Attached Grease			5	2
0	0	106-124	SOUTH WHITNEY BLVD	106-046				6	91.5	5/24/2022 10:19	TFA	TAP FACTORY ACTIVITY	6			
0	0	106-124	SOUTH WHITNEY BLVD	106-046				6	155.1	5/24/2022 10:19	TFA	TAP FACTORY ACTIVITY	6			
0	0	106-124	SOUTH WHITNEY BLVD	106-046				6	177.8	5/24/2022 10:19	TFA	TAP FACTORY ACTIVITY	6			
0	0	106-124	SOUTH WHITNEY BLVD	106-046				6	221.6	5/24/2022 10:19	TFA	TAP FACTORY ACTIVITY	6			
0	0	106-124	SOUTH WHITNEY BLVD	106-046				6	244.6	5/24/2022 10:19	TFA	TAP FACTORY ACTIVITY	6			
0	0	106-124	SOUTH WHITNEY BLVD	106-046				6	298	5/24/2022 10:19	TFA	TAP FACTORY ACTIVITY	6			
0	0	106-124	SOUTH WHITNEY BLVD	106-046				6	300.8	5/24/2022 10:19	TFA	TAP FACTORY ACTIVITY	4			
0	0	106-124	SOUTH WHITNEY BLVD	106-046				6	347.2 F02	5/24/2022 10:19	DAGS	Deposits Attached Grease			5	2
0	0	106-124	SOUTH WHITNEY BLVD	106-046			_	6	349.7	5/24/2022 10:19	AMH	Access Point Manhole				
1	0	110-163	STREET	110-162	4/25/2022	0.1	#N/A	24	0	5/24/2022 9:02	AMH	Access Point Manhole				
0	0	110-163	STREET	110-162				24	0	5/24/2022 9:02	MWL	MISCELLANEOUS WATER LEVEL			10	
0	0	110-163	STREET	110-162				24	9.3 S01	5/24/2022 9:02	DAGS	Deposits Attached Grease			0	2
0	0	110-163	STREET	110-162				24	91.1	5/24/2022 9:02	MWL	MISCELLANEOUS WATER LEVEL			20	
0	0	110-163	STREET	110-162				24	110.5	5/24/2022 9:02	MWL	MISCELLANEOUS WATER LEVEL			10	
0	0	110-163	STREET	110-162				24	176.3 F01	5/24/2022 9:02	DAGS	Deposits Attached Grease			0	2
0	0	110-163	STREET	110-162			_	24	180.6	5/24/2022 9:02	AMH	Access Point Manhole				
1	0	J05-007	CRIMSON RIDGE DR	K05-089	5/29/2012	9.9	#N/A	6	0	5/2/2022 8:27	AMH	Access Point Manhole				
0	0	J05-007	CRIMSON RIDGE DR	K05-089				6	0	5/2/2022 8:27	MWL	MISCELLANEOUS WATER LEVEL			5	
0	0	J05-007	CRIMSON RIDGE DR	K05-089				6	1 S01	5/2/2022 8:27	DAGS	Deposits Attached Grease			5	2
0	0	J05-007	CRIMSON RIDGE DR	K05-089				6	54	5/2/2022 8:27	TFA	TAP FACTORY ACTIVITY	4			
0	0	J05-007	CRIMSON RIDGE DR	K05-089				6	56	5/2/2022 8:27	TFA	TAP FACTORY ACTIVITY	4			
0	0	J05-007	CRIMSON RIDGE DR	K05-089				6	113.4	5/2/2022 8:27	TFA	TAP FACTORY ACTIVITY	4			
0	0	J05-007	CRIMSON RIDGE DR	K05-089				6	120.5	5/2/2022 8:27	TFA	TAP FACTORY ACTIVITY	4			
0	0	J05-007	CRIMSON RIDGE DR	K05-089				6	162.8	5/2/2022 8:27	TFA	TAP FACTORY ACTIVITY	4			
0	0	J05-007	CRIMSON RIDGE DR	K05-089				6	169.8	5/2/2022 8:27	TFA	TAP FACTORY ACTIVITY	4			



## Condition Assessment - Demo

>Accessible by all at the District

Observations are searchable

